

4th /08/2017

The Director of Education
and Social services
Kampala Capital City Authority
P.O Box 7010
Kampala.

**RE: REPORT FOLLOWING INSPECTION OF DELHI PUBLIC INTERNATIONAL
SCHOOL.**

Below are the findings and recommendations following the inspection of the above premises.

Date of inspection : 3rd /08/2017

Name of School : Delhi Public International School.

Postal Address : 72208 Kampala

Telephone Contacts : 0759711126/0700519423.

Nature of School : Mixed Day Nursery School.

School Status : Licensed under KCCA Directorate of Education and Social services.
License No: DES/KCCA/51/N/236.

Purpose of Inspection : Inspection of premises for suitability and conformity to be registered

Name of Proprietor : Dr. Sudhir Ruparellia

LOCATION:

The School is located on Plot 17-25 Saddler way Road ,Kiwalimu zone, Naguru 11 ward Nakawa Division, Kampala.

DESCRIPTION:

The School operates in a permanent stored building made of reinforced concrete floor with Tiled finishing, burnt brick walls plastered and rendered in a sound state and Tiled roof. Lighting and Ventilation is in accordance with the Public Health Act (Building Regulations).

ACTUAL INSPECTION

External

Apron : Provided and Sound

Walls : Plastered and painted

Windows : Sound

Doors : Sound

Fascial board : Sound

Roof : Sound

INTERNAL INSPECTION

Head Teacher's Office

Floor : Smooth finished

Floor area : 4mx4m

Walls : Plastered and painted bright

Air lighting and Ventilation : Adequate

Ceiling : Sound

Dinning shade/Indoor play area

Floor : Smooth finished

Floor area : 11mx40m

Walls : Plastered and Painted

Air lighting and ventilation : Adequate

Ceiling : Sound

Classrooms

Nursery

Floor : Smooth finished

Floor area : 12mx7m

Walls : Plastered and painted

Air lighting and ventilation : Adequate

Ceiling : Sound

UKG Classroom (A)

Floor : Smooth finished

Floor area : 12mx7m

Walls : Plastered and Painted

Air lighting and ventilation : Adequate

Ceiling : Sound

UKG Classroom (B)

Floor : Smooth finished

Floor area : 12mx7m

Walls : Plastered and painted

Air lighting and ventilation : Adequate

Ceiling : Sound

LKG classroom

Floor : Smooth finished

Floor area : 12mx7m

Walls : Plastered and painted

Air lighting and ventilation : Adequate

Ceiling : Sound

Sickbay

Floor : Smooth finished

Floor area : 7mx6m

Walls : Plastered and painted

Air lighting and ventilation : Adequate

Ceiling : Sound

General Inspection

Sanitary facilities : Four water closets are provided for
Children and two for Adults.

Hand washing facility : Provided with soap.

Water supply : There is provision of National Water and
Sewerage Corporation.

Drainage : Both waste water and storm water is catered for.


Refuse Management : Portable dustbins are provided pending final

disposal Kampala Solid Waste Management.

- Compound : Spacious, partially greened and paved.
- Games : Both indoor and outdoor games are provided. A Play ground is provided for outdoor games.
- Medical care : A well-equipped sick bay is provided being managed by a qualified.
- Meals : Children carry food from home and a school canteen is provided to supplement.
- Security : A boundary wall is provided around the premises with a gate being taken care of by security guards.
- Fire safety : Two fire extinguishers are provided and serviced.

Comment:

According to the analysis of the findings, there is no health objection to the registration of Delhi Public International School as a Mixed Day Nursery School since it meets the Public Health Act "School Building Rules"


Namaseruka Lucy
Health Inspector

